



- 8.2. Número del acta de ensayo/*Number of test report*: 0307725
9. Homologación concedida / *extendida* / ~~denegada~~ / *retirada* / *Approval granted* / *extended* / ~~refused~~ / *withdrawn* (1)
10. Lugar/*Place*: Madrid
11. Fecha/*Date*: 23-10-03
12. Firma/*Signature*:

EL SUBDIRECTOR GENERAL DE CALIDAD Y
SEGURIDAD INDUSTRIAL.
Resolución: P.D. 23-05-00

Fdo.: Antonio Muñoz Muñoz

15. Anexada a esta comunicación está una lista de documentos en el archivo de homologación depositado en los servicios administrativos los cuales serán entregados bajo petición/*Annexed to this communication is a list of documents in the approval file deposited at the administrative services having delivered the approval and which can be obtained upon request.*

(1) Táchese lo que no proceda/*Strike out what does not apply*

**DESCRIPTION OF THE VEHICLE TYPE OR TYPES FOR WHICH THE
REPLACEMENT CATALYTIC CONVERTER IS INTENDED**

EC-700-MA

Make	Model	Description	Eng- Code	OBD Compatible. YES/NO	Date From	Date to
MAZDA	MX5	1.6 i 16V Eng - B6	B6	No	04/98	08/01
MAZDA	MX5	1.8 i 16V Eng - BP	BP	No	04/98	08/00
MAZDA	MX5	1.6 i 16V 88 BHP Eng - B6	B6	No	12/95	05/01
MAZDA	MX5	1.8 i 16V 130 BHP Eng - BP	BP	No	05/94	05/01
MAZDA	MX5	1.8 i 16V Eng - BP	BP	No	04/98	08/01
MAZDA	MX5	1.6 i 16V Eng - B6	B6	No	01/95	—>
MAZDA	MX5	1.8 i 16V	B6	No	01/95	—>
MAZDA	MX5	1.6 i 16V 88 BHP Eng - B6	B6	No	04/95	12/98
MAZDA	MX5	1.8 i 16V 130 BHP Eng - BP	BP	No	04/94	04/98
MAZDA	MX5	1.6 i 16V 114 BHP Eng - B6	B6	No	01/90	08/94
MAZDA	MX5	1.6 i 16V 114 BHP Eng - B6	B6	No	01/90	08/94
MAZDA	626	1.8 i 16V Saloon, Hatchback Eng - FP	FP	No	08/91	03/97
MAZDA	626	2.0 i 16V Saloon, Hatchback Eng - FS	FS	No	08/91	03/97
MAZDA	XEDOS 6	1.6 i 16V Eng - B6	B6	No	01/92	04/94

The Reference may also be suffixed with a T. In this case, we hereby certify that these parts are made to the same specification as detailed in the technical document.